

# Material Test Report

**Report Number:** 7555/1-15  
**Issue Number:** 2 - This version supersedes all previous issues  
**Reissue Reason:** update  
**Date Issued:** 13/01/2026  
**Client:** DIXON SAND (PENRITH) PTY LTD  
, PENRITH NSW 2751  
**Contact:** Michael Munnoch  
**Project Number:** 7555/1  
**Project Name:** MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD NORTHERN ROAD, MAROOTA  
**Work Request:** 1985  
**Sample Number:** S-1985B  
**Date Sampled:** 07/01/2026  
**Dates Tested:** 07/01/2026 - 08/01/2026  
**Sampling Method:** Sampled by Client  
*The results apply to the sample as received*  
**Preparation Method:** AS 1289.1.1 - Sampling and Preparation of Soils  
**Site Selection:** Selected by Client  
**Sample Location:** Coarse Sand

Particle Size Distribution (AS1141.11.1)				
Sample Washing	Sample was Washed			
Sieve	Passed %	Passing Limits	Retained %	Retained Limits
75 mm	100		0	
63 mm	100		0	
53 mm	100		0	
37.5 mm	100		0	
26.5 mm	100		0	
19 mm	100		0	
13.2 mm	100		0	
9.5 mm	100		0	
6.7 mm	100		0	
4.75 mm	99		1	
2.36 mm	90		10	
1.18 mm	81		8	
0.6 mm	61		20	
0.425 mm	39		23	
0.3 mm	21		17	
0.15 mm	5		16	
0.075 mm	1		4	

**GEOTECH**  
**TESTING PTY LTD**  
ABN 71 076 676 321

Geotech Testing Pty Ltd  
Penrith Laboratory  
34 Borec Road Penrith NSW 2750  
Phone: (02) 4722 2744  
Email: matthew@geotech.com.au

Accredited for compliance with ISO/IEC 17025 - Testing



*M. Morley*

Approved Signatory: Mathew Morley  
Laboratory Manager  
Laboratory Number: 2734

