

Material Test Report

Report Number: 7555/1-14
Issue Number: 1
Date Issued: 12/12/2025
Client: DIXON SAND (PENRITH) PTY LTD
, PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD NORTHERN ROAD, MAROOTA
Work Request: 1875
Sample Number: S-1875B
Date Sampled: 08/12/2025
Dates Tested: 08/12/2025 - 10/12/2025
Sampling Method: Sampled by Client
The results apply to the sample as received
Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils
Site Selection: Selected by Client
Sample Location: Yellow
Material: Yellow

Particle Size Distribution (AS1141.11.1)				
Sample Washing	Sample was Washed			
Sieve	Passed %	Passing Limits	Retained %	Retained Limits
75 mm	100		0	
63 mm	100		0	
53 mm	100		0	
37.5 mm	100		0	
26.5 mm	100		0	
19 mm	100		0	
13.2 mm	100		0	
9.5 mm	100		0	
6.7 mm	100		0	
4.75 mm	99		1	
2.36 mm	94		5	
1.18 mm	86		8	
0.6 mm	52		34	
0.425 mm	24		27	
0.3 mm	10		14	
0.15 mm	2		8	
0.075 mm	1		1	



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley
Laboratory Manager
NATA Accredited Laboratory Number: 2734

