

Material Test Report

Report Number: 7555/1-10
Issue Number: 1
Date Issued: 15/09/2025
Client: DIXON SAND (PENRITH) PTY LTD
, PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
NORTHERN ROAD, MAROOTA
Work Request: 1330
Sample Number: S-1330A
Date Sampled: 12/09/2025
Dates Tested: 12/09/2025 - 15/09/2025
Sampling Method: Sampled by Client
The results apply to the sample as received
Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils
Sample Location: Coarse sand - sept
Material: Coarse sand



Geotech Testing Pty Ltd
Penrith Laboratory
34 Borec Road Penrith NSW 2750
Phone: (02) 4722 2744
Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley
Laboratory Manager
NATA Accredited Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)

Sample Washing	Sample was Washed		
Sieve	Passed %	Passing Limits	
75 mm	100		
63 mm	100		
53 mm	100		
37.5 mm	100		
26.5 mm	100		
19 mm	100		
13.2 mm	100		
9.5 mm	100		
6.7 mm	100		
4.75 mm	98		
2.36 mm	87		
1.18 mm	78		
0.6 mm	60		
0.425 mm	38		
0.3 mm	20		
0.15 mm	4		
0.075 mm	1		

