

Material Test Report

Report Number: 7555/1-22
Issue Number: 1
Date Issued: 24/08/2026
Client: DIXON SAND (PENRITH) PTY LTD
, PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
NORTHERN ROAD, MAROOTA
Work Request: 3669
Sample Number: S-3669A
Date Sampled: 13/08/2026
Dates Tested: 13/08/2026 - 14/08/2026
Sampling Method: Sampled by Client
The results apply to the sample as received
Preparation Method: In accordance with the test method
Site Selection: Selected by Client
Sample Location: Course



Geotech Testing Pty Ltd
Penrith Laboratory
34 Borec Road Penrith NSW 2750
Phone: (02) 4722 2744
Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley
NSW Laboratory Operations
Manager
Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)

Sample Washing	Sample was Washed				
	Sieve	Passed %	Passing Limits	Retained %	Retained Limits
	75 mm	100		0	
	63 mm	100		0	
	53 mm	100		0	
	37.5 mm	100		0	
	26.5 mm	100		0	
	19 mm	100		0	
	13.2 mm	100		0	
	9.5 mm	100		0	
	6.7 mm	100		0	
	4.75 mm	98		2	
	2.36 mm	88		10	
	1.18 mm	79		9	
	0.6 mm	59		20	
	0.425 mm	39		20	
	0.3 mm	23		17	
	0.15 mm	6		17	
	0.075 mm	2		4	

