## **Material Test Report**

**Report Number:** 7555/1-12

Issue Number:

Date Issued: 17/10/2025

Client: DIXON SAND (PENRITH) PTY LTD

, PENRITH NSW 2751

Contact: Michael Munnoch

**Project Number:** 7555/1

MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD NORTHERN ROAD, MAROOTA **Project Name:** 

Work Request: Sample Number: S-1493D Date Sampled: 14/10/2025

14/10/2025 - 16/10/2025 **Dates Tested:** Sampling Method: Sampled by Client

The results apply to the sample as received

Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils

Sample Location: Coarse - 10 / Oct

Report Number: 7555/1-12

Particle Size Distribution (AS1141.11.1)						
Sample Washing	Sample was Washed					
Sieve	Passed %	Passing Limits		Retained %	Retained Limits	
13.2 mm	100			0		
9.5 mm	100			0		
6.7 mm	100			0		
4.75 mm	99			1		
2.36 mm	88			11		
1.18 mm	77			11		
0.6 mm	58			19		
0.425 mm	39			19		
0.3 mm	23			16		
0.15 mm	6			17		
0.075 mm	2			5		



ABN 71 076 676 321

Geotech Testing Pty Ltd Penrith Laboratory 34 Borec Road Penrith NSW 2750 Phone: (02) 4722 2744

Email: matthew@geotech.com.au

Accredited for compliance with ISO/IEC 17025 - Testing



Approved Signatory: Mathew Morley

m. Mach

Laboratory Manager NATA Accredited Laboratory Number: 2734

