Material Test Report

Report Number: 7555/1-4

Issue Number: 2 - This version supersedes all previous issues

Reissue Reason: update

Date Issued: 17/04/2025

Client: DIXON SAND (PENRITH) PTY LTD

, PENRITH NSW 2751

Contact: Michael Munnoch

Project Number: 7555/1

Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD

NORTHERN ROAD, MAROOTA

Work Request: 596
Sample Number: S-596F
Date Sampled: 04/04/2025


Dates Tested: 04/04/2025 - 15/04/2025
Sampling Method: Sampled by Client

The results apply to the sample as received

Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils

Sample Location: Dixon Sand

Material: Medium Wash April





Geotech Testing Pty Ltd Penrith Laboratory 34 Borec Road Penrith NSW 2750 Phone: (02) 4722 2744

Email: matthew@geotech.com.au

Accredited for compliance with ISO/IEC 17025 - Testing



Approved Signatory: Mathew Morley

Laboratory Manager NATA Accredited Laboratory Number: 2734

Particle Size Distribution Sand Gravel Col Sieve Jmm) 100 90 Percent Passing 60 5 0 40 20 10 0.2 2 3 4 5 2030 100 0.1 10 Particle Size (mm)