

# Material Test Report

**Report Number:** 7555/1-2  
**Issue Number:** 3 - This version supersedes all previous issues  
**Reissue Reason:** updated  
**Date Issued:** 21/01/2025  
**Client:** DIXON SAND (PENRITH) PTY LTD  
, PENRITH NSW 2751  
**Contact:** Michael Munnoch  
**Project Number:** 7555/1  
**Project Name:** MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD  
NORTHERN ROAD, MAROOTA  
**Work Request:** 144  
**Sample Number:** S-144A  
**Date Sampled:** 13/01/2025  
**Dates Tested:** 13/01/2025 - 14/01/2025  
**Sampling Method:** AS 1141.3.1 8.4.3 - Sampling from the sides of the stockpile  
**Preparation Method:** AS 1289.1.1 - Sampling and Preparation of Soils  
**Site Selection:** Selected by Client  
**Material:** November Coarse

**GEOTECH**  
TESTING PTY LTD  
ABN 71 076 676 321

Geotech Testing Pty Ltd  
Penrith Laboratory  
34 Borec Road Penrith NSW 2750  
Phone: (02) 4722 2744  
Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley  
Laboratory Manager  
NATA Accredited Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)		
Sample Washing	Sample was Washed	
Sieve	Passed %	Passing Limits
19 mm	100	
13.2 mm	100	
4.75 mm	100	
2.36 mm	91	
1.18 mm	75	
0.6 mm	51	
0.425 mm	25	
0.3 mm	9	
0.15 mm	2	
0.075 mm	1	

