

Material Test Report

Report Number: 7555/1-2
Issue Number: 3 - This version supersedes all previous issues
Reissue Reason: updated
Date Issued: 21/01/2025
Client: DIXON SAND (PENRITH) PTY LTD
, PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
NORTHERN ROAD, MAROOTA
Work Request: 144
Sample Number: S-144C
Date Sampled: 13/01/2025
Dates Tested: 13/01/2025 - 14/01/2025
Sampling Method: AS 1141.3.1 8.4.3 - Sampling from the sides of the stockpile
Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils
Site Selection: Selected by Client
Material: November Dixon Yellow

GEOTECH
TESTING PTY LTD
ABN 71 076 676 321

Geotech Testing Pty Ltd
Penrith Laboratory
34 Borec Road Penrith NSW 2750
Phone: (02) 4722 2744
Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley
Laboratory Manager
NATA Accredited Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)		
Sample Washing	Sample was Washed	
Sieve	Passed %	Passing Limits
19 mm	100	
13.2 mm	100	
4.75 mm	100	
2.36 mm	98	
1.18 mm	92	
0.6 mm	76	
0.425 mm	43	
0.3 mm	25	
0.15 mm	14	
0.075 mm	12	

