

Material Test Report

Report Number: 7555/1-8
Issue Number: 3 - This version supersedes all previous issues
Reissue Reason:
Date Issued: 20/08/2025
Client: DIXON SAND (PENRITH) PTY LTD
, PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
NORTHERN ROAD, MAROOTA
Work Request: 1217
Sample Number: S-1217D
Date Sampled: 14/08/2025
Dates Tested: 14/08/2025 - 19/08/2025
Sampling Method: AS 1289.1.2.1 6.2 - Sampling from stockpiles
Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils
Sample Location: Maroota Quarry
Material: Coarse Sand

Geotech Testing Pty Ltd
Penrith Laboratory
34 Borec Road Penrith NSW 2750
Phone: (02) 4722 2744
Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley
Laboratory Manager
NATA Accredited Laboratory Number: 2734

Particle Size Distribution (AS1289 3.6.1)			
Sieve	Passed %	Passing Limits	
13.2 mm	100		
9.5 mm	100		
6.7 mm	100		
4.75 mm	98		
2.36 mm	85		
1.18 mm	73		
0.6 mm	53		
0.425 mm	30		
0.3 mm	14		
0.15 mm	3		
0.075 mm	2		

