

Material Test Report



Report Number: 7555/1-19
Issue Number: 1
Date Issued: 28/05/2026
Client: DIXON SAND (PENRITH) PTY LTD
 , PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
 NORTHERN ROAD, MAROOTA
Work Request: 3029
Sample Number: S-3029B
Date Sampled: 25/05/2026
Dates Tested: 25/05/2026 - 26/05/2026
Sampling Method: Sampled by Client
The results apply to the sample as received
Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils
Site Selection: Selected by Client
Sample Location: Coarse

Geotech Testing Pty Ltd
 Penrith Laboratory
 34 Borec Road Penrith NSW 2750
 Phone: (02) 4722 2744
 Email: matthew@geotech.com.au

Accredited for compliance with ISO/IEC 17025 - Testing



Approved Signatory: Mathew Morley
 NSW Laboratory Operations
 Manager

Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)					
Sample Washing	Sample was Washed				
Sieve	Passed %	Passing Limits	Retained %	Retained Limits	
75 mm	100		0		
63 mm	100		0		
53 mm	100		0		
37.5 mm	100		0		
26.5 mm	100		0		
19 mm	100		0		
13.2 mm	100		0		
9.5 mm	100		0		
6.7 mm	100		0		
4.75 mm	98		2		
2.36 mm	88		11		
1.18 mm	79		9		
0.6 mm	61		18		
0.425 mm	38		22		
0.3 mm	21		18		
0.15 mm	5		16		
0.075 mm	0		4		

