

Material Test Report

Report Number: 7555/1-13
Issue Number: 1
Date Issued: 14/11/2025
Client: DIXON SAND (PENRITH) PTY LTD
 , PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
 NORTHERN ROAD, MAROOTA
Work Request: 1633
Sample Number: S-1633D
Date Sampled: 06/11/2025
Dates Tested: 06/11/2025 - 11/11/2025
Sampling Method: Sampled by Client
The results apply to the sample as received
Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils
Site Selection: Selected by Client
Sample Location: Coarse Nov
Material: Coarse Nov

Geotech Testing Pty Ltd
 Penrith Laboratory
 34 Borec Road Penrith NSW 2750
 Phone: (02) 4722 2744
 Email: matthew@geotech.com.au

Accredited for compliance with ISO/IEC 17025 - Testing



M Morley

Approved Signatory: Mathew Morley
 Laboratory Manager
 NATA Accredited Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)		
Sample Washing	Sample was Washed	
Sieve	Passed %	Passing Limits
75 mm	100	
63 mm	100	
53 mm	100	
37.5 mm	100	
26.5 mm	100	
19 mm	100	
13.2 mm	100	
9.5 mm	100	
6.7 mm	100	
4.75 mm	99	
2.36 mm	91	
1.18 mm	85	
0.6 mm	67	
0.425 mm	45	
0.3 mm	23	
0.15 mm	6	
0.075 mm	2	

