

TEST RESULTS

DIXON SAND PTY LTD
4610 OLD NORTHERN ROAD
MAROOTA NSW 2756

Laboratory: Penrith
Job No: 7555/1

Project: MATERIAL ANALYSIS
MATERIAL TESTING - 4610 OLD NORTHERN ROAD, MAROOTA

Page 1 of 1

TEST PROCEDURE AS1141.11.1		
Material Description	Dixon White	
Sieve Analysis		
Laboratory Number	7555/1-593	
Tested By	SB	
Checked By	MM	
<u>Sieve Size</u>	Percentage Passing	Pre-treatment Standard Oven Drying Washed -
9.5mm	100	
4.75mm	100	
2.36mm	98	
1.18mm	93	
600 microns	84	
300 microns	51	
150 microns	17	
75 microns	11	
Date Sampled	Oct	
Sampling Procedure	Sampled by Client - Tested as received	
Sampling Location	Ex Maroota Quarry	

Form No: R024 Version 06 07/21 - issued by ER

Report Date



Accredited for compliance with ISO/IEC 17025 - Testing.

M Morley

12-Nov-24

Nata Accreditation Number 2734
Corporate Site Number 2727

Approved Signatory