

# Material Test Report

**Report Number:** 7555/1-13  
**Issue Number:** 1  
**Date Issued:** 14/11/2025  
**Client:** DIXON SAND (PENRITH) PTY LTD  
, PENRITH NSW 2751  
**Contact:** Michael Munnoch  
**Project Number:** 7555/1  
**Project Name:** MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD  
NORTHERN ROAD, MAROOTA  
**Work Request:** 1633  
**Sample Number:** S-1633A  
**Date Sampled:** 06/11/2025  
**Dates Tested:** 06/11/2025 - 11/11/2025  
**Sampling Method:** Sampled by Client  
*The results apply to the sample as received*  
**Preparation Method:** AS 1289.1.1 - Sampling and Preparation of Soils  
**Site Selection:** Selected by Client  
**Sample Location:** Yellow Brick Nov  
**Material:** Yellow Brick Nov



Geotech Testing Pty Ltd  
Penrith Laboratory  
34 Borec Road Penrith NSW 2750  
Phone: (02) 4722 2744  
Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley  
Laboratory Manager  
NATA Accredited Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)			
Sample Washing	Sample was Washed		
Sieve	Passed %	Passing Limits	
75 mm	100		
63 mm	100		
53 mm	100		
37.5 mm	100		
26.5 mm	100		
19 mm	100		
13.2 mm	100		
9.5 mm	100		
6.7 mm	100		
4.75 mm	100		
2.36 mm	94		
1.18 mm	88		
0.6 mm	70		
0.425 mm	44		
0.3 mm	25		
0.15 mm	13		
0.075 mm	10		

