



Client: DIXON SAND (PENRITH) PTY LTD

PO BOX 148

PENRITH NSW 2751

Project: MATERIAL ANALYSIS

MATERIAL TESTING - 4610 OLD NORTHERN ROAD, MAROOTA

Job No 7555/1 Date: 16/12/2022

Tested By: NP Checked By: AK

TEST RESULTS

Page 1 of 1

| | | Page 1 of 1 |
|--|--|--|
| TEST PROCEDURE AS1141.11.1 (DRY SIEVING), 12 | | |
| Material Description | Bricklaying SAND (Yellow) | |
| Sieve Analysis | | |
| Laboratory Number | 7555/1-509 | |
| <u>Sieve Size</u> | Percentage Passing | Pre-treatment Nil - Standard Oven Drying |
| 9.5mm 4.75mm | 100 | AS1141.12 Materials finer than 75 microns in Aggregates (by washing) % Passing |
| 2.36mm | 97 | 12.4 |
| 1.18mm | 93 | |
| 600 microns | 73 | |
| 300 microns | 19 | |
| 150 microns | 4 | |
| 75 microns | 0.9 | |
| Date Sampled | November 2022 | |
| Sampling Procedure | Sampled by Client - Tested as received | |
| Sampling Location | Ex Maroota Quarry | |

Sampling Location Ex Form No: R 025 Version 05 06/13 - issued by ER



Accredited for compliance with ISO/IEC 17025.

A Kench

19/12/2022

Approved Signatory

Nata Accreditation Number 2734 Corporate Site Number 2727

Head Office:

34 Borec Road, Penrith NSW 2750 P O Box 880 Penrith NSW 2751

Telephone: (02) 4722 2744 Facsimile: (02) 4722 2777

Prestons Laboratory:

Unit 4, 18-20 Whyalla Place, Prestons NSW 2170
Telephone: (02) 9607 6111 Facsimile: (02) 9607 6200

 $email: info@geotech.com.au \\ www.geotech.com.au$