

Material Test Report



Report Number: 7555/1-2
Issue Number: 3 - This version supersedes all previous issues
Reissue Reason: updated
Date Issued: 21/01/2025
Client: DIXON SAND (PENRITH) PTY LTD
 , PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
 NORTHERN ROAD, MAROOTA
Work Request: 144
Sample Number: S-144G
Date Sampled: 13/01/2025
Dates Tested: 13/01/2025 - 14/01/2025
Sampling Method: AS 1141.3.1 8.4.3 - Sampling from the sides of the stockpile
Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils
Site Selection: Selected by Client
Material: December Dixon Yellow

Geotech Testing Pty Ltd
 Penrith Laboratory
 34 Borec Road Penrith NSW 2750
 Phone: (02) 4722 2744
 Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley
 Laboratory Manager
 NATA Accredited Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)		
Sample Washing	Sample was Washed	
Sieve	Passed %	Passing Limits
19 mm	100	
13.2 mm	100	
4.75 mm	100	
2.36 mm	98	
1.18 mm	94	
0.6 mm	81	
0.425 mm	48	
0.3 mm	27	
0.15 mm	15	
0.075 mm	13	

