

# Material Test Report

**Report Number:** 7555/1-3  
**Issue Number:** 1  
**Date Issued:** 19/02/2025  
**Client:** DIXON SAND (PENRITH) PTY LTD  
, PENRITH NSW 2751  
**Contact:** Michael Munnoch  
**Project Number:** 7555/1  
**Project Name:** MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD  
NORTHERN ROAD, MAROOTA  
**Work Request:** 275  
**Sample Number:** S-275G  
**Date Sampled:** 11/02/2025  
**Dates Tested:** 11/02/2025 - 17/02/2025  
**Sampling Method:** Sampled by Client  
*The results apply to the sample as received*  
**Preparation Method:** AS 1289.1.1 - Sampling and Preparation of Soils  
**Site Selection:** Selected by Client  
**Material:** February Dixon White



Geotech Testing Pty Ltd  
 Penrith Laboratory  
 34 Borec Road Penrith NSW 2750  
 Phone: (02) 4722 2744  
 Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley  
 Laboratory Manager  
 NATA Accredited Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)			
Sample Washing	Sample was Washed		
Sieve	Passed %	Passing Limits	
75 mm	100		
63 mm	100		
53 mm	100		
37.5 mm	100		
26.5 mm	100		
19 mm	100		
13.2 mm	100		
9.5 mm	100		
6.7 mm	100		
4.75 mm	100		
2.36 mm	97		
1.18 mm	93		
0.6 mm	82		
0.425 mm	66		
0.3 mm	45		
0.15 mm	15		
0.075 mm	8		

