

## TEST RESULTS

DIXON SAND PTY LTD  
4610 OLD NORTHERN ROAD  
MAROOTA NSW 2756

Laboratory: Penrith  
Job No: 7555/1

Project: MATERIAL ANALYSIS  
MATERIAL TESTING - 4610 OLD NORTHERN ROAD, MAROOTA

Page 1 of 1

TEST PROCEDURE AS1141.11.1	
Material Description	Dixon Coarse
Sieve Analysis	
Laboratory Number	7555/1-596
Tested By	SB
Checked By	MM
<u>Sieve Size</u>	Percentage Passing
9.5mm	100
4.75mm	100
2.36mm	92
1.18mm	85
600 microns	66
300 microns	23
150 microns	4
75 microns	1
Date Sampled	Oct
Sampling Procedure	Sampled by Client - Tested as received
Sampling Location	Ex Maroota Quarry

Form No: R024 Version 06 07/21 - issued by ER

Report Date



Accredited for compliance with ISO/IEC 17025 - Testing.

M Morley

12-Nov-24

Nata Accreditation Number 2734  
Corporate Site Number 2727

Approved Signatory