

Material Test Report

Report Number: 7555/1-22
Issue Number: 1
Date Issued: 24/08/2026
Client: DIXON SAND (PENRITH) PTY LTD
, PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
NORTHERN ROAD, MAROOTA
Work Request: 3669
Sample Number: S-3669D
Date Sampled: 13/08/2026
Dates Tested: 13/08/2026 - 14/08/2026
Sampling Method: Sampled by Client
The results apply to the sample as received
Preparation Method: In accordance with the test method
Site Selection: Selected by Client
Sample Location: Yellow - Brick

GEOTECH
TESTING PTY LTD
ABN 71 076 676 321

Geotech Testing Pty Ltd
Penrith Laboratory
34 Borec Road Penrith NSW 2750
Phone: (02) 4722 2744
Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley
NSW Laboratory Operations
Manager

Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)					
Sample Washing	Sample was Washed				
Sieve	Passed %	Passing Limits	Retained %	Retained Limits	
75 mm	100		0		
63 mm	100		0		
53 mm	100		0		
37.5 mm	100		0		
26.5 mm	100		0		
19 mm	100		0		
13.2 mm	100		0		
9.5 mm	100		0		
6.7 mm	100		0		
4.75 mm	100		0		
2.36 mm	97		3		
1.18 mm	91		5		
0.6 mm	75		16		
0.425 mm	50		24		
0.3 mm	33		17		
0.15 mm	20		14		
0.075 mm	14		5		
Clay and Fine Silt (AS 1141.33)				Min	Max
Volume of Clay and Silt (%)		8			

