

Material Test Report

Report Number: 7555/1-18
Issue Number: 1
Date Issued: 06/05/2026
Client: DIXON SAND (PENRITH) PTY LTD
 , PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
 NORTHERN ROAD, MAROOTA
Work Request: 2812
Sample Number: S-2812A
Date Sampled: 29/04/2026
Dates Tested: 29/04/2026 - 04/05/2026
Sampling Method: Sampled by Client
The results apply to the sample as received
Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils
Site Selection: Selected by Client
Sample Location: Coarse Sand

Geotech Testing Pty Ltd
 Penrith Laboratory
 34 Borec Road Penrith NSW 2750
 Phone: (02) 4722 2744
 Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

M Morley

Approved Signatory: Mathew Morley
 NSW Laboratory Operations
 Manager

Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)					
Sample Washing	Sample was Washed				
Sieve	Passed %	Passing Limits	Retained %	Retained Limits	
13.2 mm	100		0		
9.5 mm	100		0		
6.7 mm	100		0		
4.75 mm	98		2		
2.36 mm	87		12		
1.18 mm	74		13		
0.6 mm	56		18		
0.425 mm	36		19		
0.3 mm	20		17		
0.15 mm	5		14		
0.075 mm	2		3		

