

Material Test Report

Report Number: 7555/1-5
Issue Number: 1
Date Issued: 19/05/2025
Client: DIXON SAND (PENRITH) PTY LTD
, PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
NORTHERN ROAD, MARROOTA
Work Request: 769
Sample Number: S-769C
Date Sampled: 12/05/2025
Dates Tested: 12/05/2025 - 13/05/2025
Sampling Method: Sampled by Client
The results apply to the sample as received
Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils
Sample Location: Dixon Sand
Material: May Coarse



Geotech Testing Pty Ltd
Penrith Laboratory
34 Borec Road Penrith NSW 2750
Phone: (02) 4722 2744
Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley
Laboratory Manager
NATA Accredited Laboratory Number: 2734

Particle Size Distribution (AS1289 3.6.1)

Sieve	Passed %	Passing Limits
75 mm	100	
63 mm	100	
53 mm	100	
37.5 mm	100	
26.5 mm	100	
19 mm	100	
4.75 mm	99	
2.36 mm	93	
1.18 mm	80	
0.6 mm	52	
0.425 mm	24	
0.3 mm	9	
0.15 mm	2	
0.075 mm	2	

