

AUTHORIZED MATERIALS

All materials (e.g. rock, sand, gravel, and topsoil) will be obtained from areas which have been cleared for cultural resources and have been determined to contain no significant historic properties.

The following list of rock sources on or near the Heart Butte Unit were previously reviewed and approved by DKAO Archeologists.

MORTON COUNTY

1. Knife River Corporation, 4025 County Road 82, Mandan, ND. SW $\frac{1}{4}$ Sec. 30 & N $\frac{1}{4}$ NW $\frac{1}{4}$, Sec. 31, T139N, R81W & SE $\frac{1}{4}$, Sec. 25, T139N, R82W.
2. Iron Horse Scoria (formerly Schatz/Gerving). SE $\frac{1}{4}$ NE $\frac{1}{4}$ SE $\frac{1}{2}$ & E $\frac{1}{2}$ SE $\frac{1}{4}$ SE $\frac{1}{4}$, Sec. 10 & W $\frac{1}{2}$ SW $\frac{1}{4}$ SW $\frac{1}{4}$, Sec. 11, T138N, R89W.
3. Edd Bachler Farm. Rock piles in sections 22, 23, 26, T137N, R87W.
4. Kinnischtzke Sand Pit and Gravel Pile in Morton County, T139N, R88W Sec. 7 & 18 BCA 2018-59.

STARK COUNTY

1. Fischer Sand and Gravel Company, 10535 32nd St. SW, Dickinson, ND. SW $\frac{1}{4}$, Sec. 9, T140N, R95W.

GRANT COUNTY

1. GT-1001. NW $\frac{1}{4}$ NE $\frac{1}{4}$, Sec. 28, T135N, R89W.
2. GT-1006 (Roth). NW $\frac{1}{4}$ SE $\frac{1}{4}$ & N $\frac{1}{2}$ SW $\frac{1}{4}$, Sec. 11, T133N, R90W.
3. Iron Horse Scoria (Formerly Schatz/Gerving). NW $\frac{1}{4}$ NW $\frac{1}{4}$, Sec. 4, T137N, R88W.

HETTINGER COUNTY

1. Blickensdorfer Field Clearing Piles. ND SHPO REF.: 13-1141 BOR. NW $\frac{1}{4}$, Sec. 13, T136N, R92W. SW $\frac{1}{4}$, Sec. 17 & W $\frac{1}{2}$, Sec. 20 & NW $\frac{1}{4}$, Sec. 29, T136N, R91W.