

TOTAL PHOSPHORUS WATER TESTING 2000 2007 * 2011 2012 2013 2014 2015 2016 2017 2018 2019 2020 *** 2021**

CAMPGROUND INLET	11.50	41.00	35.00	28.00	53.00	33.00	34.00	27.60	30.00	51.00	30.00	32.00	18.00
DEEP SPOT UPPER LEVEL (1.5 M)	9.50	9.30	12.00	15.00	12.00	12.00	8.00	9.70	11.00	9.00	8.00	7.00	14.50
DEEP SPOT MIDDLE LEVEL (4.5M)	16.50	50.00	48.00	28.00	9.00	14.00	10.00	10.00	13.00	12.00	10.00	8.00	12.80
DEEP SPOT BOTTOM (8M)	8.50	15.00	12.00	15.00	32.00	18.00	no sample	19.20	24.00	14.00	27.00	22.00	24.50
DUMP BRANCH	11.00	18.50	27.00	23.00	32.00	21.00	15.00	11.00	11.00	15.00	12.00	24.00	7.80
ROARING BROOK (NE BRANCH)	sample spill	35.50	32.00	20.00	29.00	26.00	25.00	19.50	21.00	32.00	25.00	92.00	20.20
DAM OUTLET	7.00	10.50	11.00	11.00	11.00	10.00	9.00	7.50	8.00	10.00	8.00	12.00	12.30
SANDY POINT (Bridge)	6.50	12.00	14.00	10.00	12.00	10.00	17.00	10.60	14.00	20.00	14.00	25.00	10.40
NE BRANCH 2, BELOW BRIDGE		N/A										121.00	
TEST 2 , LOWER ROARING BROOK		27.00	AVERAGE POOR EXCESSIVE									181.00	19.40
TEST 4, UPPER ROARING BROOK		15.00	11 - 20	21 - 40	40+							54.00	15.60
TEST 8, RABBIT HOLLOW BRANCH		20.00										26	19.00
TEST 6, POWER LINE BRANCH		13.00										47	6.60

*** In 2007 & 2020 extra testing was done on Roaring Brook to determine the source of the excessive spike in TP.