








SERVICE OFFERINGS














CIVIL WORKS













ROAD CONSTRUCTION EXPERIENCE

Gravel Road Length	Start Date	End Date	Contract Period (months)	Scope of Work under Prime Contract	Role
153.64 Km (D19 Kawambwe Mulwe road 58.3 Km D96 Mwewa Road 95.27 Km)	November, 2006	December 2009	36 Months	Design, Rehabilitation, Improvement and Maintenance of Main and District Roads in Luapula Province Package 3: • Heavy and Light Bush Clearing • Road Formation and Gravelling • Mitre Drain provision • Installation of Culverts • Building of wing and head walls • Replacing of damaged culverts	Prime Contractor
150 Km	November, 2006	December, 2009	38 Months	Design, Rehabilitation, Improvement and Maintenance of Main and District Roads in Northern Province Package 3: • Heavy and Light Bush Clearing • Road Formation and Gravelling • Mitre Drain provision • Installation of Culverts • Building of wing and head walls • Replacing of damaged culverts	Prime Contractor
180 Km	17 [™] October, 2005	July, 2006	8 Months	Periodic Maintenance of the Mansa to Luwingu Road Project (M3) in Luapula Province: • Heavy and Light Bush Clearing • Road Formation and Gravelling • Mitre Drain provision • Installation of Culverts • Building of wing and head walls • Replacing of damaged culverts • Periodic Maintenance of the 86 Km	Prime Contractor

SABLE TRANSPORT & CONSTRUCTION

CORPORATE EXPERIENCE

ROAD CONSTRUCTION EXPERIENCE

	Gravel Road Length	Start Date	End Date	Contract Period (months)	Scope of Work under Prime Contract	Role
	86 Km	29th August, 2008	28th September, 2009	7 Months	Periodic Maintenance of the 86 Km Napumdwe to Blue Lagoon Works Heavy Grading Re-gravelling Vegetation Control Bush Clearing Drainage works Construction of Culvert Headwalls Wingwalls and cleaning of Culverts	Prime Contractor
が 一	114 Km	21st October,2008	June, 2009	8 Months	Rehabilitation and Maintenance of the 114 Km D134 Petauke to Chilongozi and Ukwimi Sonja road in Eastern Province • Heavy Grading • Re-gravelling • Vegetation Control • Bush Clearing • Drainage works • Construction of Culvert Headwalls • Wingwalls and cleaning of Culverts	Prime Contractor
	86.1 Km	October, 2008	March 2009	5 Months	Rehabilitation and Periodic Maintenance of the 86.1 Km Mununga to Nkoshya Mukunsa Road Project in Luapula Province • Heavy Grading • Re-gravelling • Vegetation Control • Bush Clearing • Drainage works • Construction of Culvert Headwalls • Wingwalls and cleaning of Culverts	Prime Contractor

SABLE TRANSPORT & CONSTRUCTION

CORPORATE EXPERIENCE







