STATE OF FLORIDA **DEPARTMENT OF HEALTH COUNTY HEALTH DEPARTMENT PUBLIC POOL AND BATHING PLACE INSPECTION REPORT**



Correct By: Next Inspection

Re-Inspection Date: None

1 of 2

Facility Information

RESULT: Satisfactory

Permit Number: 05-60-05031

Name of Facility: Marina Village Condo SPA Address: 580 S Banana River Drive City, Zip: Merritt Island 32952

Type: Spa-Type Pools

Owner: Marina Village Condominium Association of Brevard, Inc. Person In Charge: Marina Village Condo Phone: (321) 576-8250

PIC Email:

Pool Operator: 365 Pools Phone: (321) 784-2091

Inspection Information

Purpose: Routine Begin Time: 02:30 PM Inspection Date: 7/24/2025 End Time: 03:30 PM

Additional Information

22. Free Chlorine 2.0	VOLUME 780
23. pH 7.4	POOL LOAD 5
24. Chlor. Stablilizer 0	FLOW RATE 50
33. Flowmeter 45	NIGHT SWIM No
34. Thermometer 101	FILTER TYPE CP

Items checked are not in compliance with Chapter 386 or 514, Florida Statutes, or Chapter 64E-9 or 64E-10, Florida Administrative Code. These violations must be corrected by the date indicated to avoid closure, administrative fines, or other legal actions. Florida Building Code (FBC) violations are reported to the local building official, and depending upon risk severity, the Department of Health may close the pool or rescind the operating permit.

Violation Markings

POOL AREA 1. Water Clarity/Algae Control 2. Deck/Walkways 3. Tile/Pool Finish 4. Depth Markers-FBC 5. Handrail/Ladder-FBC 6. Step Markings-FBC 7. Suction Outlets-514.0315(1)	17. Rules Posted 18. Certification SANITARY FACILITIES 19. Supplies 64E-10, FAC 20. Clean 64E-10, FAC WATER QUALITY 21. Approved Test Kit 22. Free Chlor./Brom.	32. Vacuum Cleaner-FBC 33. Flowmeter 34. Thermometer 35. Pressure/Vacuum Gauge 36. Equip. Room 37. Cross Connection 38. Gas Chlorine EqFBC 39. Waste Water - FBC
9. Lighting	∑ 23. pH 24. Chlor. Stabilizer	40. D.E. Separator-FBC 41. Other Equipment
	25. Spa Requirements-ORP	42. Equip. Change-FBC
11. Diving Board-FBC	EQUIPMENT ROOM	43. Approved Chemicals
12. Pool Cover	26. Wading Pool-Quick Dump	44. Maintenance Log
13. Pool Side Shower-FBC	27. Water Level/Control	45. Inspection Posted
POOL SAFETY	28. Disinfection Feeder/Generator	46. Safety-514.0315(2)
14. Life Hook(s) w/Pole	29. pH Feeder	47. Fences/Gates- FBC
15. Life Ring(s) w/Rope	Chem. Container Label-FBC	48. Other
16. Safety Line	31. Filter / Pump	49. Other

NOTE: It is unlawful to modify a public pool or its equipment without prior approval from the local building department and submitting an application to DOH.

Client Signature:

Inspector Signature: dren Bypon

Emailed: No one available to sign. Spoke mailed: with michael on the phone.

Form Number: DH 920 04/16 05-60-05031 Marina Village Condo SPA

STATE OF FLORIDA DEPARTMENT OF HEALTH COUNTY HEALTH DEPARTMENT PUBLIC POOL AND BATHING PLACE INSPECTION REPORT



2 of 2

General Comments

All observed violations (23, 25 and 29) were corrected on-site during inspection. Please call if you have any questions.

Facility notes: Resurfaced 2021. Gravity for main and therapy (collector tank), direct for skimmer (ELP). Waterway 12x12" WWP 640-472 grate expires 03/04/2028. 1 set of safety equipment. 1HP non-variable recirc pump, 3HP therapy pump (emergency shut-off switch with alarm and sign). ORP-Rolachem RC554XP, Cl-RolaChem RC103SC, pH-RC103RC. StaRite PLM200 cartridge filter. Aquapro electric and StaRite gas heaters (1 each) plumbed in-line with each other and bypass valves. 1 light. 1 skimmer. Shower on deck. Wall returns and static line (north side of bottom wall next to skimmer equilizer). 1 figure-4 handrail (step/bench markings-green SR). 15 minute timer with clock. Hours Dawn to Dusk. Max Depth 3FT. Test kit and log with equipment.

Email Address(es): tom@bpdavis.com; linda@bpdavis.com; mvbrdpresident@gmail.com; info@365pool.com;

DOH Web Page For Pools: http://www.floridahealth.gov/environmental-health/swimming-pools/index.html

Violations Comments

Violation #23. pH

At start of routine inspection the tested pH was too high (8.4), but was adjusted and corrected on-site by pool operator.

CODE REFERENCE: pH. 64E-9.004(1); 64E-9.017(1). The pH in all pools shall be maintained between 7.0 and 7.8, inclusive. Pool owner must prohibit pool use when water quality is outside these parameters.

Violation #25. Spa Requirements-ORP

At start of inspection the ORP controller was disconnected, but was corrected on-site by pool operator (reconnected and turned on).

CODE REFERENCE: Spa 104°F, ORP, Oils. 64E-9.008(8) & (12). Spa pools have a maximum temperature of 104° F. Spas must have an ORP auto controller to aide in pH and disinfection with water potential between 700 and 850 millivolts, unless spa pool is exempt by age & size. Oils, minerals, and lotions may not be used by patrons.

Violation #28. Disinfection Feeder/Generator

At start of inspection the pH adjustment feeder was not able to dispense chemical, but was repaired and corrected on-site by pool operator.

CODE REFERENCE: Disinfection Feeder. 64E-9.008(10)(e); 64E-9.017(1). A properly sized disinfection feeder and/or generator shall be provided. Electrical pumps must be electrically interlocked with the recirculation pump. Feeders/generators must be certified under NSF/ANSI 50.

Inspection Conducted By: Ivan Bryson (26992) Inspector Contact Number: Work: (321) 615-9399 ex.

Print Client Name: Date: 7/24/2025

Inspector Signature:

Client Signature

Emailed: No one available to sign. Spoke Michael on the phone.

Form Number: DH 920 04/16 05-60-05031 Marina Village Condo SPA