

HISTORICAL EXTERIOR RESTORATIVE WORK, including dismantling four decorative balconies and salvaging terracotta units for reinstallation and/or replacement with glass fiber reinforced concrete units to match the original terra cotta; dismantling a decorative balustrade and salvaging cast stone units for reinstallation and/or replacement in kind above the entrance; removing and resetting and/or replacing decorative cast stone and brick elements in kind at the ground floor; repairing spalled and cracked terra cotta and cast stone units whit cementitious repair mortar and grout and finish coatings as required, and repointing terra cotta and cast stone mortar joints; replacing cast stone window sills, steel lintels and associated brickwork; removing non-decorative masonry chimney and reconstructing the chimney at a lower height above the finish roof; reconstructing parapets and corners with new brick and mortar; replacing existing metal parapet cladding, coping and railings; reconstructing penthouse parapets as required, replacing existing metal wall cladding; replacing roofing membranes and flashing systems and refurbishing and replacing skylights.

HISTORICAL WINDOW RESTORATIVE WORK, including the replacement of the existing windows throughout the building, including multi-light and one cover one wood and aluminum windows, excluding the stairwell windows, at the basement through the 17<sup>th</sup> floors and penthouse level, with single, paired and tripartite aluminum window units; the installation of six-over-six double hung windows and one-over-one double hung frosted glass windows at the South, East and West elevation; the installation of six-over-six and eight-over-eight double hung windows and one-over-one double hung frosted glass windows at the North elevation.



## 585 WEA

585 WEST END AVENUE NEW YORK, NY 10024

LANDMARKS: RIVERSIDE-WEST END HISTORIC DISTRICT









**HISTORICAL EXTERIOR RESTORATIVE WORK**, including dismantling decorative and salvaging terracotta cornice units for reinstallation and/or replacement with glass fiber reinforced concrete units to match the original terra cotta.



LANDMARKS: RIVERSIDE-WEST END HISTORIC DISTRICT



