


FlyGuys

Bay Alarm Redding, CA. Annotation Report



Created on August 10, 2024

Captured on December 14, 2023



Distance ↘

Label	Title	Length	Horizontal	Vertical	Slope	Surface
1 ●	North Parking	21.91 ft	21.85 ft	-1.62 ft	-4.23°, 7.4%	22.07 ft
2 ●	Untitled	24.42 ft	24.42 ft	0 ft	0°, 0.01%	24.42 ft

Area ↗

Label	Title	Horizontal Length	Horizontal Width	Area	Surface Area
3 ●	Water Leak #1	--	--	29.48 ft ²	30.00 ft ²
4 ●	Water Leak #2	--	--	35.66 ft ²	39.50 ft ²
5 ●	Plants growing in drain	--	--	14.07 ft ²	11.68 ft ²
6 ●	Remove Antenna from Location	--	--	7.97 ft ²	0 ft ²
7 ●	Glass Broken- Suite D	--	--	8.80 ft ²	0 ft ²
8 ●	Remove Mail Slot	--	--	1.20 ft ²	0.44 ft ²
9 ●	Replace Dumpster Gate	--	--	78.51 ft ²	188.15 ft ²
10 ●	Possible Gas Leak	--	--	16.38 ft ²	18.90 ft ²
11 ●	Water Leak #3 (Cooler Feed)	--	--	25.01 ft ²	69.99 ft ²

Volume ▲

Label	Title	Area	Cut	Fill	Net	Tolerance
12 ●	Shop Area	924.29 ft ²	3.71 y ³	3.48 y ³	-0.23 y ³	0 ft
13 ●	Break Room	245.86 ft ²	0.22 y ³	0.05 y ³	-0.17 y ³	0 ft
14 ●	Lobby Area	737.02 ft ²	0.63 y ³	1.15 y ³	0.52 y ³	0 ft
15 ●	Conference Room	405.03 ft ²	0.08 y ³	0.43 y ³	0.35 y ³	0 ft
16 ●	Server Room	54.30 ft ²	0.04 y ³	0.01 y ³	-0.03 y ³	0 ft
17 ●	Ops Manager	100.42 ft ²	0 y ³	0.12 y ³	0.12 y ³	0 ft
18 ●	Secured Area (Gate)	1885.32 ft ²	3.27 y ³	12.36 y ³	9.09 y ³	0 ft