Process Safety Management Compliance Issues

A Photographic Tour of Worst Chemical Manufacturing Nowhere, USA



Gayle Nicoll, PhD, REP, ASP, CSP Senior Scientist AECOM Technical Solutions 1555 North RiverCenter Dr., Suite 214 Milwaukee, WI 53212 414-944-6080 (office) 608-359-5923 (cell)

Gayle.Nicoll@aecom.com

Site Visit

Hypothetical Site

No real location, no real identity

Anonymous Photo

ID What's Wrong

Discuss How To Correct



Building Exterior



Chemical Unloading Area




Photo Credit: CSB, Media Room, Photo Gallery, MGPI Investigation, https://www.csb.gov/photos/

Site Access



Flammable/Combustible Containment



Hot Work




Photo Credit: CSB, Media Room, Photo Gallery, Partridge-Raleigh Investigation, https://www.csb.gov/photos/

Flammable Liquid Storage



Tank Exterior



Flammable/Combustible Tank



Emergency Lighting



Tank Venting



Building Interior



Braided Hose



Photo Credit: CSB, Media Room, Photo Gallery, DuPont, Belle, WV Investigation, https://www.csb.gov/photos/

Pumping Flammable Material



Page 15 AECOM

Discharge to Sewer



Blowout Wall



Combustible Dust



Flammable/Combustible Interior



Look Up



Identity Crisis



Water Bath



Flammable/Combustible



Smoke Hatch




LOTO



Page 25

Combustible Liquid Storage



Hazardous Chemical Storage



Tank Venting




Out of Service Slings



Compressed Air Line



Sewer




Page 31

Flammable/Combustible Area



VFD Wiring Issue





Electrical



Live Busbar



Do You See It?



Do You See It?




Hazardous (Classified) Location



Hazardous (Classified) Location




Do You See It?



Flammable/Combustible



Inside Tank



Conclusion



Look around your facility with a fresh set of eyes.



Focus on:

- Electrical
- PM Completion



Don't get complacent

An Ounce of Prevention...



Photo Credit: CSB, Media Room, Photo Gallery, Husky Energy, Superior, WI, 2018, https://www.csb.gov/photos/