



True North Home Inspection, LLC
218-206-2080
www.truenorthhomeinspection.com

PRE-WINTER REPORT
VISUAL DOCUMENTATION ONLY

This Report provides Visual Documentation of the property at the specified address at the date and time these photographs were taken.

This Report is for reference of exterior areas on this property not visually accessible due to snow cover.

*Driveway/Roadways *Aprons *Walkways *Patios *Docks *Retaining Walls *Grade & Drainage
*Foundation Walls *Decks/Balconies/Boardwalks *Steps/Stairs/Stoops *Roofs – including Skylights,
Attic/Plumbing/Exhaust Vent Flashing, Chimney/Electrical Mast Venting, *Gutters and Downspouts

ADDRESS: 1234 My Street, Any Town, MN

DATE: September 7th, 2019

TIME: 3:00 pm

TEMPERATURE: 56° F

WEATHER: Partly sunny and breezy

GROUND CONDITION: Wet



Property Overview

- Main Residence
- 2 - Stall Detached Garage
- Additional Garage



Main Residence



Main Residence - continued



2 – Stall Garage



Additional Garage

