

**Pipeline Investigation and Cleaning  
Common at Sinnott Farm  
Bloomfield, CT  
September - October 2005**


**FOR:**

**Common at Sinnott Farm  
P.O. Box 681  
Bloomfield, CT 06002**

**BY:**

**New England Pipe Cleaning Company  
Division Heitkamp, Inc.  
99 Callender Road  
Watertown, CT 06795**

13-782 500 SHEETS FILLER 5 SQUARE  
42-381 50 SHEETS EYE-EASE 5 SQUARE  
42-382 100 SHEETS EYE-EASE 5 SQUARE  
42-383 200 SHEETS EYE-EASE 5 SQUARE  
42-384 100 SHEETS EYE-EASE 5 SQUARE  
42-385 200 SHEETS EYE-EASE 5 SQUARE  
42-386 100 SHEETS EYE-EASE 5 SQUARE  
42-387 200 SHEETS EYE-EASE 5 SQUARE  
42-388 100 SHEETS EYE-EASE 5 SQUARE  
42-389 200 SHEETS EYE-EASE 5 SQUARE  
Made in U.S.A.



Watertown, CT 06795

# CLOSED CIRCUIT TELEVISION INSPECTION REPORT

Bloomfield, CT 05-03-50-38

## AREA

[illegible]

## ABBREVIATIONS

OSJ - OFFSET JOINT  
OJ - OPEN JOINT  
LJ - LEAKING JOINT  
DJ - DROPPED JOINT

SC - SERVICE CONNECTION  
LS - LEAKING SERVICE  
PS - PROTRUDING SERVICE  
LAS - LEAKING AROUND SERVICE

BRKP - BROKEN PIPE  
CRKP - CRACKED PIPE  
PSC - PROTRUDING SC

PSC - PROTRUDING SC

Watertown, CT 06795

# CLOSED CIRCUIT TELEVISION INSPECTION REPORT

Bloomfield, CT 05-03-50-38

## AREA

[illegible]

## ABBREVIATIONS

OSJ - OFFSET JOINT  
OJ - OPEN JOINT  
LJ - LEAKING JOINT  
DJ - DROPPED JOINT

SC - SERVICE CONNECTION  
LS - LEAKING SERVICE  
PS - PROTRUDING SERVICE  
LAS - LEAKING AROUND SERVICE

BRKP - BROKEN PIPE  
CRKP - CRACKED PIPE  
PSC - PROTRUDING SC

Watertown, CT 06795

## AREA

BRKP - BROKEN PIPE  
CRKP - CRACKED PIPE  
PSC - PROTRUDING SC

Watertown, CT 06795

Bloomfield, CT 05-03-50-38

AREA

[illegible]

OSJ - OFFSET JOINT  
OJ - OPEN JOINT  
LJ - LEAKING JOINT  
DJ - DROPPED JOINT

SC - SERVICE CONNECTION  
LS - LEAKING SERVICE  
PS - PROTRUDING SERVICE  
LAS - LEAKING AROUND SERVICE

BRKP - BROKEN PIPE  
CRKP - CRACKED PIPE  
PSC - PROTRUDING SC