PROJECT: CROPLAND

BEFORE

LOCATION: KENNETT SQUARE, PA



PROJECT DESCRIPTION

This project involved installing a grassed waterway in a field that is currently being row cropped. The operator does an excellent job implementing soil health practices such as no-till and cover crops, however, it was not enough to prevent the formation of a gully through the low area in the field.

RESOURCE CONCERNS

- Gully Erosion
- Loss of Topsoil
- Sediment Deposition



PROJECT: CROPLAND

AFTER

COMPLETION DATE: NOVEMBER 2020





SERVICES PROVIDED

- Conservation Plan Development
- Site Survey
- Design/Engineering
- · Project Bidding
- · Construction Checks/Certification
- Project Management

BEST PRACTICES INSTALLED

- Grassed Waterway (Parabolic Shaped)
 - Allows the water to flow through the field in a non-erosive manner

