



Pleasant Valley

C O R P O R A T I O N

Construction Facility Management Real Estate


Guardian Angel Church
Kitchen Remodel
Copley OH
Progress Photos
8/18/2023

Progress Summary

- Progress
 - Week 6
 - Masonry walls cleaned and paint removed where applicable
 - Vapor barrier applied to existing masonry walls
 - Framing of new walls completed
 - In wall mechanical rough-in started
 - Reconfiguration of existing electrical in serving area underway





1093 MEDINA ROAD SUITE 100 MEDINA, OH
44256 Office Ph: 330-239-0176 Fax: 330-239-4117



1093 MEDINA ROAD SUITE 100 MEDINA, OH
44256 Office Ph: 330-239-0176 Fax: 330-239-4117










1093 MEDINA ROAD SUITE 100 MEDINA, OH
44256 Office Ph: 330-239-0176 Fax: 330-239-4117












1093 MEDINA ROAD SUITE 100 MEDINA, OH
44256 Office Ph: 330-239-0176 Fax: 330-239-4117





1093 MEDINA ROAD SUITE 100 MEDINA, OH
44256 Office Ph: 330-239-0176 Fax: 330-239-4117



1093 MEDINA ROAD SUITE 100 MEDINA, OH
44256 Office Ph: 330-239-0176 Fax: 330-239-4117

