



**Alpine Springs Water Distribution**  
P.O. Box 7871  
Santa Rosa, CA 95407  
(707) 708-2939  
support@alpinespringswater.biz

## Spring Water Quality Report

Here is a detailed table of our water testing results:

*Last updated: May 2024*

Constituent	Test Result (mg/L)
Aluminum	ND
Arsenic	ND
<b>Calcium</b>	<b>5.4</b>
Chlorine	ND
Copper	ND
Fluoride	ND
Iron	ND
Lead	ND
Manganese	ND
<b>Magnesium</b>	<b>2.5</b>
Mercury	ND
Nickel	ND
<b>Potassium</b>	<b>1.9</b>
Selenium	ND
Silver	ND
<b>Sodium</b>	<b>4.4</b>
Thallium	ND
Zinc	ND
<b>pH</b> Above 7 is Alkaline Below 7 is Acidic	<b>7.5</b>
<b>TSD</b>	<b>75</b>

*\*ND = Not Detected*