
Iron County Earth Fissures
Escalante Valley Earth Fissures
Cedar Valley Earth Fissures
Study Areas
Miles
0
4
7
11
14
IRON COUNTY
T30S R18W
T30S R11W
T31S R20W
T31S R19W
T31S R18W
T31S R17W
T31S R16W
T31S R15W
T31S R14W
T31S R13W
T31S R12W
T31S R11W
T31S R10W
T31S R9W
T31S R8W
T31S R7W
T31S R6W
T31S R5W
T32S R20W
T32S R19W
T32S R18W
T32S R17W
T32S R16W
T32S R15W
T32S R14W
T32S R13W
T32S R12W
T32S R11W
T32S R10W
T32S R9W
T32S R8W
T32S R7W
T32S R6W
T33S R20W
T33S R19W
T33S R18W
T33S R17W
T33S R16W
T33S R15W
T33S R14W
T33S R13W
T33S R12W
T33S R11W
T33S R10W
T33S R9W
T33S R8W
T33S R7W
T33S R6.5W
T33S R6W
T34S R20W
T34S R19W
T34S R18W
T34S R17W
T34S R16W
T34S R15W
T34S R14W
T34S R13W
T34S R12W
T34S R11W
T34S R10W
T34S R9W
T34S R8W
T34S R7W
T34S R6W
T35S R20W
T35S R19W
T35S R18W
T35S R17W
T35S R16W
T35S R15W
T35S R14W
T35S R13W
T35S R12W
T35S R11W
T35S R10W
T35S R9W
T35S R8W
T36S R20W
T36S R19W
T36S R18W
T36S R17W
T36S R16W
T36S R15W
T36S R14W
T36S R13W
T36S R12W
T36S R11W
T36S R10W
T36S R9W
T36S R8W
T37S R16W
T37S R16W
T37S R14W
T37S R13W
T37S R12W
T37S R11W
T37S R10W
T37S R9W
T37S R8.5W
T37S R8W
T38S R8W
T38S R12W
T38S R11W
T38S R10W
Minersville
Beryl
Paragonah
Pardwan
Modena
Summit
Enoch
Newcastle
Cedar City
Brian Head
Enterprise
Kanarraville
New Harmony
Central
Pine Valley
Duck Creek Village
Alton
Panguitch Lake
Navajo Lake
The data contained herein is for general display purposes only and may not be entirely accurate. No liability is assumed as to the accuracy of the data delineated herein. Any corrections should be directed to the Iron County Information Systems Department or the Iron County GIS.
Date Exported:12/1/2020 3:11 PM
H:\GIS\J_PROJECTS\0_2020\047_Geologic Maps\GeoHazards.aprx